



ATTACHING TAIL

SHADED PART
IS NOT COVERED





WING ATTACHING


WING CLIPS ARE
CEMENTED TO THE
BOTTOM OF THE
WING EDGES



TAIL BOOM




FREE WHEELING



CUT ALONG
DOTTED LINES
AFTER BLADES
HAVE BEEN CUT

$\frac{1}{8}$ " CAMBER

PROPELLER



THRUST BEARING