



GRAINED MEMBERS AROUND OUTLINE OF FUSELAGE ARE KEEL PIECES - PLACE ON PLAN AND ASSEMBLE BULKHEAD HALVES ON THEM. HALF OF FUSELAGE AT A TIME.